

Service Bulletin

SB # 224

Published: 20/12/2019

By: Service/DJ

- ☐ Generally
- ☐ Dishwashers
- ☐ Bedpan Washer Disinfectors
- ☒ Instrument Washer Disinfectors
- ☐ Process Solution

- ☐ To be exchanged as soon as possible
- ☐ To be exchanged at the next maintenance
- ☐ To be exchanged at the usual service interval
- ☒ Information

Change made from machine #

63394

IQ6 Check valve drying unit

We have added a flange on the check valve for the drying unit to ensure better reliability.

New part no: 2908670



Previous part no.: 2908112



These instructions are intended for guidance purposes only. They have been developed to support authorised technicians, trained by KEN HYGIENE SYSTEMS A/S, or by a KEN HYGIENE SYSTEMS A/S approved training partner, with the installation and maintenance of, products manufactured by KEN HYGIENE SYSTEMS A/S.

The instructions are subject to change without notice.